

# USEPA Region VII Analytical Services Request (ASR) Form

Activity No.: G2133 Date: 6/22/95  
 Site Name, City, & State: Carter Carburetor  
 EPA Project Manager: Dan Homera  
 Section/Branch: ERRP Phone No.: 913-551-5088  
 Contractor Contact: Joe Davis  
 Contractor: Ecology and Environment Phone No.: 314 298 0577  
 Projected Sample Delivery Date: 6/29/95  
 Funding Program Element: Cercla

## Request Summary:

No. of Samples	Matrix	Group/Parameter Name	Group/Parameter MGP Code
9	wipe	PCB's	H09
12	Soil	PCB's	S16
2	oil	PCB's in oil	H02
1	water	PCB's	W24
13	Soil	PCB's in Concrete	S16
5	Soil	PCB's in Wood Chips	S16
4	wipe	TCDD / PCDD / PCDF	H12
5	Dust	TCDD / PCDD / PCDF	S82

Use additional pages as needed for clarity.

Levels Of Interest Are Specified (mark one): In The QA Document-☐  
 or On The Back-☒

## Special Requirements or Comments:

3 Week Turnaround requested

Carter Carburetor  
1111. MOD00822601  
 Break: 103  
 Other: ASR Form  
6-22-95

NOTE: Submit This Form To RQAM/ENSV ~~30 Days Before~~ Sample Delivery

## Approvals:

[Signature] 6/22/95  
 EPA Project Manager (Date) EPA Branch or Section Chief (Date)

## The Following Is Completed By ENSV Personnel ONLY

QA Document: ☐-Generic QAPP ☐-Site Specific QAPP ☐-Other: \_\_\_\_\_

## Concurrences:

RQAM: \_\_\_\_\_ Comment: \_\_\_\_\_

Chief, LABO: \_\_\_\_\_ Comment: \_\_\_\_\_

## Laboratory Assignment:

## Scheduled Completion:

- ☐-Region VII
- ☐-ESAT
- ☐-CLP
- ☐-RECAP
- ☐-Other
- ☐-Routine:
  - Non-CLP = 4 weeks
  - CLP = 8 weeks
- ☐-Other: \_\_\_\_\_
- Date: \_\_\_\_\_

## Distribution:

- ☒ EPA Project Manager
- ☒ Chief, LABO/ENSV
- ☐ Chief, GNAN/LABO
- ☐ Chief, ORGN/LABO
- ☒ Chief, CLPM/LABO
- ☒ Data Coordinator
- ☒ RSCC
- ☐ Other: \_\_\_\_\_

(Use Additional Copies Of This Form As Needed)

Activity No.: 621JJ

Site Name: Carter Carburetor

(Revised February 1993

**USEPA Region VII Analytical Services Request (ASR) Form**

Activity No.: G2133 Date: 6/22/95  
 Site Name, City, & State: \_\_\_\_\_  
 EPA Project Manager: \_\_\_\_\_  
 Section/Branch: \_\_\_\_\_ Phone No.: \_\_\_\_\_  
 Contractor Contact: \_\_\_\_\_  
 Contractor: \_\_\_\_\_ Phone No.: \_\_\_\_\_  
 Projected Sample Delivery Date: \_\_\_\_\_  
 Funding Program Element: \_\_\_\_\_

**Request Summary:**

No. of Samples	Matrix	Group/Parameter Name	Group/Parameter MGP Code
4	Soil	Metals	SM

Use additional pages as needed for clarity.

Levels Of Interest Are Specified (mark one): In The QA Document-☐  
 or On The Back-☒

**Special Requirements or Comments:**

3 week Turnaround requested

**NOTE: Submit This Form To RQAM/ENSV 30 Days Before Sample Delivery**

**Approvals:**

[Signature] 6/22/95 \_\_\_\_\_  
 EPA Project Manager (Date) EPA Branch or Section Chief (Date)

**The Following Is Completed By ENSV Personnel ONLY**

QA Document: ☐-Generic QAPP ☐-Site Specific QAPP ☐-Other: \_\_\_\_\_

**Concurrences:**

RQAM: \_\_\_\_\_ Comment: \_\_\_\_\_

Chief, LABO: \_\_\_\_\_ Comment: \_\_\_\_\_

**Laboratory Assignment:**

**Scheduled Completion:**

**Distribution:**

☐-Region VII \_\_\_\_\_  
☐-ESAT \_\_\_\_\_  
☐-CLP \_\_\_\_\_  
☐-RECAP \_\_\_\_\_  
☐-Other \_\_\_\_\_

☐-Routine:  
     • Non-CLP = 4 weeks  
     • CLP = 8 weeks  
☐-Other: \_\_\_\_\_  
 Date: \_\_\_\_\_

☒ EPA Project Manager  
☒ Chief, LABO/ENSV  
☐ Chief, GNAN/LABO  
☐ Chief, ORGN/LABO  
☒ Chief, CLPM/LABO  
☒ Data Coordinator  
☒ RSCC  
☐ Other: \_\_\_\_\_

## (Use Additional Copies Of This Form As Needed)

Activity No.: \_\_\_\_\_ Site Name: \_\_\_\_\_

(Revised February 1993)